

**CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
LOS ANGELES REGION**

101 CENTRE PLAZA DRIVE
MONTEREY PARK, CA 91754-2156
(213) 266-7500
FAX: (213) 266-7600

SFUND RECORDS CTR
2166-98181



SFUND RECORDS CTR
88147308

January 4, 1995

Mr. Jody Hill
Nupla Plastic Corporation
11912 Sheldon Street
Sun Valley, Ca. 91754

**WELL INVESTIGATION PROGRAM - NESTED SOIL GAS PROBES SAMPLING
(FILE NO. 111.0788)**


We have reviewed your "Monitoring of Nested Soil Gases (Second Episode)" dated September 29, 1994, prepared by Environmental Support Technologies, Inc., and have the following comments:

1. Soil vapor results identified trichloroethene (TCE) up to 52 $\mu\text{g/l}$, 1,1,1-trichloroethane up to 6 $\mu\text{g/l}$, cis-1,2-dichloroethene up to 5 $\mu\text{g/l}$. Neither freon 113 nor 1,1-dichloroethene was detected in this round of sampling. This September's results show a lesser degree of concentrations than the previous soil gas sampling.
2. However, another round of soil vapor sampling in the month of March will be in order to establish a trend that the decreasing results are not because of seasonal changes or one time excursion.
3. We request that soil vapor sampling be in accordance with requirements outlined in our "Workplan Requirements for Soil Gas Investigation".

Please notify us at least ten (10) days before commencing the subsurface investigation, so Regional Board staff can be present.

Three (3) copies of the technical report is due to this Regional Board April 27, 1995.

If you have any questions regarding this matter please contact Mr. Jimmie Woo at (213) 266-7591.


HUBERT H. KANG
Senior Water Resource
Control Engineer

cc: ~~Mr.~~ David Seter, U.S. EPA Region IX
Mr. Tom Klinger, Los Angeles County - Forester and Fire Warden
Mr. Kirk Thomson, Environmental Support Technologies